

Our cover illustrations

Front cover

Survey of unknown date of the condition of Cleveland Bridge, Bath, apparently prepared for the repair and strengthening of the bridge in the 1920s. The surveyor reported, *inter alia*:


x fastenings for the parapet, broken in many instances

a.a.a. shew where joints occur
scale of half-inch to one foot.

Back cover

Detail from the survey showing a section of the parapet and road plates.

Courtesy of Bath City Record Office, archivist Colin Johnston.



BIAS

JOURNAL 27